Suzanne Steab - February 2010 Inspection Report

Page 1 of 1 C0070020 X

From:

Karl Houskeeper

To:

kit@emerytelcom.net

Date:

3/23/2010 8:34 AM

Subject:

February 2010 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Horizon February 2010.pdf

Kit,

Attached is the February 2010 inspection report for the Horizon Mine.

Thanks,

Karl



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection: Company Kit Pappas Manager of Environmental/Engineering

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070020
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, February 16, 2010
Start Date/Time:	2/16/2010 10:00:00 AM
End Date/Time:	2/16/2010 1:00:00 PM
Last Inspection:	Thursday, January 14, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 31 Deg. F. InspectionID Report Number: 2272

Accepted by: jhelfric

3/22/2010

Permitee: HIDDEN SPLENDOR RESOURCES INC

Operator: HIDDEN SPLENDOR RESOURCES INC

Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral	Ownershi	n Tv

Types of Operations

1,577.00	Total Permitted	☑ :	Federal 🗹	Underground
9.50	Total Disturbed		State	Surface
	Phase I		County	Loadout
	Phase II	☑ 1	Fee \square	Processing
	Phase III		Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's	Signature:
-------------	------------

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Tuesday, February 16, 2010

Date

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 16, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Commont	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	Lvaluateu	Mor Applicable		
2.	Signs and Markers	<u> </u>		<u> </u>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<u> </u>		<u> </u>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<u> </u>	П	V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations			<u> </u>	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	<u> </u>	<u> </u>		
	Coal Mine Waste, Refuse Piles, Impoundments	<u> </u>	<u> </u>		
8.	Noncoal Waste	<u> </u>		<u> </u>	
9.	Protection of Fish, Wildlife and Related Environmental Issues		<u> </u>		
10.	Slides and Other Damage				
11.					
12.	Backfilling And Grading				
13.		$\frac{\square}{\square}$			
14.	Subsidence Control				
15.	Cessation of Operations	<u>_</u>			
	Roads: Construction, Maintenance, Surfacing	$\overline{\Box}$			
	Roads: Drainage Controls		П		
17.	Other Transportation Facilities	<u>_</u>			
	Support Facilities, Utility Installations				
	AVS Check				_
	Air Quality Permit	<u> </u>			-
	Bonding and Insurance				
	Other			$\overline{}$	

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 16, 2010

Page 3 of 3

2. Signs and Markers

The mine identification sign is located at the point of public access to the permit area. The sign is in legible and contains the required information.

4.a Hydrologic Balance: Diversions

The main diversion to the side of the access road leading to the office/bathhouse area is building with ice laden sediment. The diversion needs to be monitored as the temperatures increase to ensure that the amount of sediment in the diversion does not exceed the design standard of the diversion.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Large piles of snow are being stored on the coal storage pad above the sediment pond and on the edge of the sediment pond.

8. Noncoal Waste

The dumpster containing noncoal waste is full and needs to be hauled off site.